

1 建设项目及水土保持工作概况

序号	监测点位	影像	坐标
4	沂河 164+600-165+800 新筑堤防		118° 35'34.8784"
			35° 44'20.7914"
5	马家庄砂料场及附近堤防		118° 34'38.9978"
			35° 38'47.2240"
6	石浪头段堤防		118° 31'56.4688"
			35° 36'26.5767"
7	李家独树段堤防		118° 31'39.5902"
			35° 35'04.6054"

1 建设项目及水土保持工作概况

序号	监测点位	影像	坐标
8	李家独树砂料场		118° 31'51.4896"
			35° 35'01.6183"
9	铜井河支流堤防		118° 31'03.7280"
			35° 34'51.2082"
10	施工 2 标堤防加固段堤防		118° 32'34.1656"
			35° 31'08.8631"
11	沂南排水沟支流堤防		118° 31'26.8057"
			35° 30'38.1792"

1 建设项目及水土保持工作概况

序号	监测点位	影像	坐标
12	施工 2 标堤防加固段建筑物		118° 32'09.3112"
			35° 31'01.6640"
13	新兴河支流堤防		118° 28'27.9138"
			35° 25'38.1833"
14	前东河料场及附近干流堤防		118° 28'46.2344"
			35° 25'38.2603"
15	西流河附近干流堤防		118° 30'10.3204"
			35° 27'20.3642"

1 建设项目及水土保持工作概况

序号	监测点位	影像	坐标
16	沭河北段防汛道路		118° 53'17.2343"
			35° 44'30.6414"
17	沭河右 25+497-28+701 加 固堤防段		118° 48'36.3523"
			35° 30'33.3924"
18	马沟河旁干流堤防 及险工		118° 42'32.9120"
			35° 21'54.1650"
19	沭河 K3+000 堤防		118° 42'04.9483"
			35° 21'38.1641"